Water Services Ltd

Appliance Inspection & Test Record

Customer: Am Water Services | **Engineer:** Richard Lecarde II

Location: VAN WP25 FMF Scan + Kieran | **Test Date:** 15/7/26

Test Instrument: EZ XPAT Plus | **Serial Number:** WB44/1661 | **Retest Date:** 15/16/26 | **Page:** 1 of 1

ID	Appliance Description	Voltage (V)	Rating (W or A)	Fuse (A)	Class (I/II)	Visual √/x	Earth Continuity (Ω)[1]	Insulation Resistance (MΩ)[2]	Leakage Current (mA)	Function √/x /Load (kVA or A)	Polarity √/x	Comments	Overall Pass/Fail √/x
SP017	Sub Pump 1	110			II	✓		>20.00	0.09			Good	✓
SP004	Sub Pump 2	110			II	✓		>20.00	0.21			Good	✓
SB010	Splitter Box	110			II	✓		>20.00	0.07			Good	✓
ER021	Ext Reel	110			II	✓		>20.00	0.23			Good	✓
SL018	Site Lights	110			II	✓		>20.00	0.08			Good	✓
KX010	Plug Ext	240		13	13	✓		>20.00	0.03			Good	✓

[1] Measured value should not exceed (0.1 + R) Ω (X) - Fail (N/C) - Not Checked (N/A) - Not Applicable

[2] Measured value should not be less than 1.0MΩ for Class I & 2.0MΩ for Class II

JG ENTERED 20 JUL 2026